SeGMo-System

High degree of planning certainty for worldwide export

-5)

With our plug-and-play solution, you can automate every feed axis. Our UL-certified system components offer you the following advantages:

> SeGMo-Positioning

Fully automatic positioning drives reduce the set-up times and costs during every format change

> SeGMo-Box

C

LISTED

c **FL**[®] us

Decentral control units reduce the load on your network architecture

> SeGMo-Connect

Pre-assembled hybrid cables minimise the cabling effort

> SeGMo-Lib

Block library for the efficient integration of components into the PLC supports your Industry 4.0 measures with active condition monitoring

> SeGMo-Support Tool

Preconfigure and test the positioning system straightforwardly using the recommended software

 Recipe software including support
 Modernise your machines and set them up quickly without mistakes using saved formats



Finding solutions. Founding trust.

SeGMo-Positioning

Positioning drives for feed axes with Aluminium or stainless steel housing

SeGMo-Connect

Easy cabeling

Cable outlet with M23 coupling Cable outlet with M17 coupling M17 connector Cable outlet with connection terminals Cable outlet



SeGMo-Box

Decentral control system as compact device for 5 positioning drives or modular control unit for up to 17 positioning drives




SeGMo-Lib

Integration without programming

Comprehensive function block library for:

- > TIA-Portal / Step 7 / SCOUT
- > Studio 5000 / RSLogix
- > Automation Studio
- > TwinCAT
- > CODESYS 3.x / SoMachine V4






SeGMo-Support Tool

Our recommendation: Configure and set up the complete SeGMo-System on the PC

What do you need to have?

- PC with free USB port, current version of .Net framework The application can be used without extensive installation
- > Connection to USB interface of the SeGMo-Box
- Graphic user interface with tool tips for ease of operation



Data exchange with the PC

- Component parameters are imported and exported independently of the interface to the PLC
- > Parameters are stored in the drives
- Parameter sets are stored on the PC, e.g. for identical machines

In this way machines with identical operating parameters can be configured quickly and reliably.

Commissioning and setting up

- Functions of the PowerDRIVEs are tested independently of the PLC connection and complex program routines
- > Manual movement of PowerDRIVEs
- Interface preparation for PLC connection (Note-ID / address of the DHCP server, etc.)

rains. Anybus setting	Drives 1.6 Paras	ater Dru	1					
Drive 1								
eFuse 1								
Fuse	· reset		Position	17098	Target P	osition		0 incr
Drive	descrives		Velocity	0	Target V	wooty [)	0 inch
Voitage	25745	niV						
Current	95	mA	Target Position Target Velocity					
Pt Trip Current	5800		POS	(5	1665	STOP	
5800	and Linear		Honsing	(100	N N	-00	
Managine	0x0000000			5.94	Mn	Max	Detault	
Warning .			Velocity	1666	0	2870	1666	
Enor e	0x00000000		Acceleration	2525	132	26581	2525	OK.
	Fault result		Deceleration	2525	132	20581	2525	OK.
	-		Quick stop	6645	664	88454	0645	OK :
			Max Current	7500	0	7500	7500	OK

Data exchange with the PLC

- Parameter setting for the SeGMo-System directly in the PLC programming environment
- Simple parameter control: motor current, speed, warnings, etc.
- Active condition monitoring supports your Industry
 4.0 activities

All steps for setting up the axis can be executed directly in your machine's PLC or conveniently on the PC.



Lenord, Bauer & Co. GmbH Dohlenstrasse 32, 46145 Oberhausen, Germany Tel. +49 (0)208 9963-0 Fax +49 (0)208 676292

info@lenord.de www.lenord.com